







Type 5090
Type 90120




X - 10 mm



10 mm






1
2



5 mm

click 1



click 2




1

2



3




Y mm



Y - 10 mm



10 mm






1
2

5 mm



click 1


click 2




4

5


6





Type 9090
Type 120120




Z mm




Z - 10 mm



10 mm




5 mm



click 2

click 1



1

2

3